

Bradford







Q1 IRON PIN 1921 PROFILE &
PLAN F76 Consultant set May. 14/1 w/washer #7060

F 5-12-86 Lored out front Boil in
intersection, checked ties & lower
= d corner pin to approx 2' deep

C Set 1/2" IP with 2" Alum Cap LS 7060
Consultant 5/21/99

O Consultant found 3/4" IP 5-21-99

A Consultant set survey on 11-4-04 File 2005-0037
Fnd nail w/washer 2-19-08. File 2008-0321



(See end of Bradford for more
S.C. TIES)