



Sec 15-95-13

COR B Stone 1925 Line For DAYTON
Twp. Road Const. Found Nail over Spk + Retied



COR B1 Stone 1745 Line For DAYTON
Twp. Road.
Drove NAIL IN STONE

COR C Drove I.P. 259' N and in line
with B & B1

Cor B Replaced spike with 1/2" rebar 11-12-03. File 2003-3491



P. Herold set 11-12-03




PC STA 457+53.9

1988 Alpha Plans 6-89 Set PK


Got good reading with detector tied in 6-88

Dayton



PT STA 466+14.8

Good reading w Metal detector - Set PK 6-29-88 P. Anderson tied in 6-88



REF To P1 STA 482+03.04 Found stem of SPK Tied in 6-88