


- A 1/2" Iron Pin 1922
- B 1/2" Iron Pin
Found Iron Pin & tied off
south edge of Highway #18 4-12-66
- A Found lead plug 2/79
7-9-85 IDOT Alum Core
- B Found iron pin 2/79
7-9-85 no ties under 100' IDOT
- C Found steel corner post in concrete. 2/79
Found steel corner post 5-12-03 File 2003-1479

C 4" steel po.


Fredericksburg Township

Sec 10


Cont. 34' 24' Cont. Post




Cor A




Cor. A 2/79



Cor B



Cor. B 2/79
Consultant 12/16/92



Found steel corner post in concrete
Cor. C 2/79
P. Herold retied 5-12-03