

Frederickburg Township

Sec 11

- A 1/2" Iron Pin 1222 FAP 177
- B 1/2" Iron Pin 1922
- A Found lead plug 2/79 7-9-85 IDOT
Retied 5-12-03 File 2003-1480
- B Found lead plug 2/79 7-9-85 IDOT
Found 3" alum. disk 5-12-03 File 2003-1478
- C Set standard monument 6" deep 2/79
Found 2" alum. cap (IDOT) 5-12-03 File 2003-1481
- O File 2003-1479

39.87



39.55

80.22

C
2" Alum. Cap

B
3" disk

A
3" disk




Cor B

7-9-85

P. Herold retied 5-12-03

Cor A



Cor. A 2/79

R.O.W. PIN

5" rebar

70.82 57.78


5'-0"

Sec. 11
Hwy 19


COR. A. R.O.W. Pin

7-9-85 IDOT

P. Herold retied 5-12-03



Cor. B 2/79



Cor C

Set standard monument 6" deep.
P. Herold retied 5-12-03