

New Hampton

A Dug 5'x7'x6' hole found nothing
Erdman set PI after regrading File 2003-1503

A, Set 1/2" rebar w/cap 4-8-04. File 2004-0832

B I.P. 1952
retied 6-13-61

Y see last page

C Bluestone 6-8-26 5" deep

Set 1/2" bar w/cap n. side wood stake 10-21-96 BK/62 pp 272


O Erdman set 1/2 rebar 4-30-99

Found 1/2" rebar w/cap 12-7-05 File 2005-2663

X Erdman Engineering retied 4-30-99

Found 1/2" rebar w/cap 12-7-05 File 2005-2663

| | | | |
|-------|----------|---------------|----------|
| | 20.32 ch | 40.97 | Stone |
| | 40.00 ch | Stone | 4x6x12 |
| 40.88 | 40.24 ch | 40.72 | 40.28 ch |
| | | 40.54 ch | 40.24 |
| | 20.52 ch | 41.42 ch | Stone |
| | 41.00 ch | Stake | |
| | 40.25 ch | 40.71 ch | |
| | 41.50 ch | 42.40 ch | Stones |
| | | Stone 16x8x10 | |
| | | A 1/2" rebar | |
| | | B 1/2" rebar | |
| | | C Brick | |
| | | D Tile | |



New Hampton Twp. Section 18

Cor. O Consultant tied in 7/12/95


Cor. C, Set 1/2" rebar w/ 2" aluminum cap LS 2060

NH Twp Sec 23


Cor. C E 1/4 corner set 1/2" rebar w/ 2" alum. cap
LS 7060

Cor Y NH Twp Sec 15

Set 1/2" rebar w/ 2" alum. cap 12-9-05 File 2005-2664




Cor. O
Consultant 7/12/95




Lyle Tekippe 4-00


Cor. C




Cor. C 95-12
Lyle Tekippe set 12-00



Cor. K Sec 10-95-12
P. Herold and 5/8" pipe w/ alum cap
5-22-07 File 2007-1047



Cor. A Sec 10-95-12
P. Herold set 1/2" rebar w/ 2" alum
cap 5-22-07 File 2007-1047



Cor. Y
P. Herold set 12-8-05
Sec 15