

UTICA S.

B

I.P. 5-1-54 Found IRON STONE
Placed I.P. ON S. SIDE
Found I.P. 10-1-54
Found 1" pin 12" deep 12-20-96. BK 162 pg 496

C

IRON pin 5-3-54 SET I.P. SPHT FENCE
Found Hub & placed I.P. 5-11-62
Found I.P.

C1

FOUND STONE MAY 1953
Found 1" iron pipe 12-20-96. BK 162 pg 497

A

Consultant Found T BAR as set
on survey by H.D. Blessing recorded
in book 114 page 176-177 on File
in the Recorder's office

STONE

4003

4003

STONE

49-04

4010 1/2

STONE

STONE

STONE

STONE

STONE 39.96

4010 1/2

STONE

BOUNDARY

4023

4023

STONE

FARTHEN
WARE WORK


Sec 34

Found IRON STONE

Placed I.P. ON S. SIDE


Found I.P. 10-1-54

Found 1" pin 12" deep 12-20-96. BK 162 pg 496



Cor. B


P. Herold retired 12-20-96



Cor A

Consultant 5/17/96


Sec 34



Cor. C

Found 5-11-62

L. Erdman retired 12-10-96



COR. C1