

Utica North

COR. A IRON PIN Found 7-15-52

Found I.P. Retied 7-6-64. Set PK 9-9-08

B IRON PIN 1954 5' E. of bridge, 10' from N/E cor. post guard,

10.3' from S/E cor. post rail. Set nail 10-16-90.

Find PK 5-15-95 - BK 15-8 pg 71. Set PK in new mat

9-9-08

B' COR. PIN WAS SET IN 1955

FOR CONST. OF RELOCATION

C. 1927 IRON PIN FOUND IRON PIN

RETIED 1954 CONSULTANT

O Consultant set 1/2" rebar 2-18-00 File 2005-0292

X Consultant set I.P. 5/95

C1 Consultant 5/95

STONE & BR 40.00 GAS PIPE

