

A STONE IRON PIN 1921 PROFILE & PLAN F.A.P. #76
 Found 2 1/2" aluminum DOT Marker 1-4-05. File 2006-0086
 STONE
 O IRON PIN 1921 PROFILE & PLAN F.A.P. #76
 Consult set Survey Mark nail 11-4-04 File 2005-0039
 O I IRON PIN 1921 PROFILE & PLAN F.A.P. #76
 Consultant set Survey Mark nail 11-4-04 File 2005-0041
 F Consultant found 1" pipe 11-4-04 File 2005-0038
 COR H' Set 1/2" rebar w/cap 5-3-04 File 2004-1023
 COR G Set Iron Pin for Const. Found 1" IP 4-10-04 File 2004-0583
 COR H Consultant reset 1 1/2" pipe 11-4-04 File 2005-0040
 ONLY 4-22-55, Found 1" Iron pin 4-10-04
 File 2004-0584
 O Fnd nail washer 2-19-08. File 2008-0321
 Stone 1" IP
 OIP X O'
 STONE G IP 2590.6
 H' J 2676.3
 Limestone 1" IP A 2642.6 B
 B Set rebar by existing rock 1-4-06 File 2006-0085
 Cor X Consult set 3/8" x 1' capped spike 11-4-04 File 2005-0041
 J Set Magnail at prorated distance File 2006-0087
 See After Bradford 36 For More (B, F, & J)

