

Sec. 24-75-1A

A Set 5/8" rebar w/alam. cap 10-5-07. File 2007-1964

COR. A STONE 8-29-32 31.8 To EITHER COR. POINT

Found Stone Placed I.P. 4-27-57 HARP

COR. B IRON PIN 5-18-29 Found Stone - Set 3-22-07
STONE File 2007-0571

IRON PIN 4-27-59 Found Stone Raised
STONE DUG 8x3x3 (4 1/2" I.P.)

COR. C IRON PIN 1927 Hole could NOT FIND COR. 8-18-61

See after Sec. 36 Dayton Twp.

COR. C1 IRON PIN 1927 Found Stone SET STONE
STONE OR TAPOR TAND I.P. ON
8-21-61 DUG 8x4x4 hole could NOT FIND
DANA, CLEVELAND, MURTAUGH above RESET IRON PIN FROM EXISTING FOUND
STONE SET BLUE STONE 8x8x8



COR. F2 IRON PIN 1927 and IRON PIN.
FOUND PIN + BLUE STONE SET 8-18-61
Set mag nail w/washer 10-5-07. File 2007-1963.

COR. Y IRON PIN Retired 8-18-61
DANA, CLEVELAND, MURTAUGH

Found PK 11-29-04 File 2004-2708

set PK in new mat 7-27-05

E, Sec after Sec 36 Dayton Twp



Chickasaw

Sta 2267 6 D.B

For More Ties to C1 See Page after Section 36 Dayton Twp

Cor Y Set PK 6-22-61 R. Anderson

Retired 8-18-61 DANA
S. Stein fast retied 11-29-04
Set PK in mat 7-27-05 J.R.M.C

Cor F2
P. Herold set 10-5-07

Sec 24-95-14.

Cor. C1 Lined in with $\frac{1}{2}$ " Road West and $\frac{1}{2}$ " of Road South used metal detector and found spike 6" below Gravel 6-88 JFM

C Set $\frac{5}{8}$ " rebar w/alum. cap 10-5-07. File 2007-1964

E1 Set $\frac{5}{8}$ " rebar w/alum cap 10-5-07. File 2007-1965

