

Sec. 14-95-13



COR B Iron Pin 5-4-29 Set Iron Pin
Found IP and Retied 10/4/93 Consultant

COR C. Iron Pin 5-24-29 Set Iron Pin
Found IP and Retied 10/4/93 Consultant
Ref PI STA 482+03.04 Sec Section
15 Dayton Twp.

Cor. B set 1/2" rebar over 1.5' deep pin 11-29-03 File 2003-3342

Cor. A set 1/2" rebar w/cap 11-12-03 File 2003-3491

Cor. E' set 1/2" rebar w/cap 11-12-03 File 2003-3492




COR B

Retied 1-12-95
Retied 12-16-95
P. Herold set 10-29-03

REF. PT. 494+26.2


Good Reading with Metal
detector Set ties 6r88
Set PK
6-79 R. Anderson



COR C

Retied Consultant
10/4/93

4 Road
west



Dayton

