

Fredricksburg Township
Sec. 2

B Stone with bolt on West side


C Stone Found & retied 4-9-56

A 27.4 to West Gate Post


24.6 to East Gate Post

Set 1/2" rebar 5-12-03 File 2003-1480


B Found iron pin 12" deep. Set iron pin over 2/99



Cor. B
Retied 4-12-56




Cor. C.
Retied 4-9-56



Found iron pin 12" deep
Set iron pin over.

Cor. B 2/99

Retied 6/29/94 by Consultant



Cor. A
Pittenger set 5-12-03

Nail in Willow

