



New Hampton
 A. Stone Brick 3' west of Fence Line to South
 Dug large hole unable to locate
 10-8-64

B Found Stone. Resot $\frac{1}{2}$ " rebar 9-30-96 BK
 160 pg 431

C Stone not found, found original post.
 see BK 160 pg 429




Cor. A



Cor. B

T. Loringham retied 9-30-96



Cor. C

T. Loringham retied 9-30-96

Iron Stone
 43' NE Cor Post
 46.5 NW " "

Gas Pipe Iron

Brick & Iron Rod Stone Gas Pipe Iron Stone & Iron
 Stone Gas Pipe stoned Brick Iron