

Stanley Ave



A Found I.P. 6-12-61

A₁ Set I.P. at SW 1/4 - 1/4 Cor for Const. only 6-12-61

O Found I.P. 36" deep in line with fence west. 6-12-61 File 2001-1444

X L Erdman set 1/2" rebar 7-12-01. File 2001-1442


Y L Erdman set 1/2" rebar File 2001-1443




Cor A 6-12-61

Cor A₁
Set I.P. for Const.
6-12-61


Sec 20



Cor. O
Retied 9-98 JF, TR, ID
L Erdman retied 7-01 File 2001-1444



Cor. Y
Set 1/2" rebar 7-01



Cor. X
L. Erdman set 7-12-06