


Stapleton

COR. C Consultant Found 12" Granite Stone 18" Deep on the north side of an old fence post, also check this position with other corners in section, consultant bent a 1/2" x 4'-0" rebar in the configuration shown



Sec 36

