

Jacksonville S

B I.P. 1925 S.C.T. I.P.

Consultant 10/27/95

A P. Herold setied $\frac{5}{8}$ " pipe w/cap 2-26-03

File 2003-0591

C Consultant Found $\frac{5}{8}$ " Rebar

With cap 7549 from previous survey

recorded April 28, 1990 Deeds Book 122 Page 13

10-18-02

O File 2002-2528 Set $\frac{1}{2}$ " rebar w/alum. cap 0.21' N. of Stone

X I File 2002-2528 Found $\frac{5}{8}$ " pipe w/alum. cap 10-18-02

X J File 2002-2529 Found $\frac{5}{8}$ " pipe w/cap 10-18-02

X Y Set $\frac{1}{2}$ " rebar w/alum. cap 0.34' west of stone 4-4-02

File 2002-0869

| | | | | |
|------------------------------|--------|--------|--------|--------------|
| Boulder & broken crockery | 2527.8 | 2522.9 | 2522.9 | Stone 2529.7 |
| Stone | 38.49 | | | Iron |

| | | | | |
|-----------------|-------|------------|-------------|-------------------|
| Stone & I.P. | 39.02 | 1/2" rebar | Stone 39.24 | Stone gas pipe |
| | | | Iron | |

| | | | | |
|---------|-------|------------|-------|---------------|
| Boulder | 26.07 | 1/2" rebar | 26.07 | Iron stake |
| | | | Stone | |

| | | | | |
|-------------------------|-----|-------|-------|----------------------|
| | | 26.07 | 34.26 | 38.96 |
| | X I | | X J | |
| Boulder Iron beneath | | 35.56 | | |
| | A | 20.50 | 20.50 | Stone I.P. |
| | | | | $\frac{5}{8}$ " pipe |

Sec. 29

